

Atalla Product Versions

Product	Recommended Release	Date Released	
All HP Atalla Ax150(V) network security processors (includes A10150, A10150V, A9150, A9150V, A8150, A8150V)	3.50C	January 2008	Customers should upgrade to release 3.50C or higher as soon as possible; 3.60C has a significant issue and is not recommended at this time.
All HP Atalla Ax100(V) network security processors (includes A10100, A10100V, A9100, A9100V, A8100, A8100V)	3.50	January 2008	Releases below 3.50 are not compatible with Ax150 replacement NSPs; 3.60 has a significant issue and is not recommended at this time. Note: End of support life for Ax100 products has been established as 1 July 2010
HP Atalla Secure Communications Assistant - 2	1.0 or 2.0	August 2006	No need to upgrade units running release 1.0
HP Atalla Secure Communications Assistant (Compaq branded)	2.3	May 2004	Compatible with SCA-2
HP Atalla Secure Communications Assistant (HP branded)	2.4	August 2004	Compatible with SCA-2
HP Atalla Remote Management Utility	1.4	August 2006	Release 1.2 or higher is OK for SCA; 1.4 recommended for SCA-2 features
HP Atalla Trusted Print Center	3.1	March 2005	
Boxcar	AAJ/AAK	June 2009	AAJ for NonStop Integrity systems; AAK

			for other NonStop systems
Atalla Secure Remote Manager	AAB	June 2006	
Compliance Log Warehouse	2.0.1	August 2009	

Support for A10000, A9000, A8000 and SCT was discontinued in February 2005. Support for A10100, A10100V, A9100, A9100V, A8100, A8100V and A8100/Websafe will be discontinued 1 July 2010.